

# Two Man Class Rules 2021

1. Can have 4" x 4" bumper welded on front with bumper skin over it.
2. 4 hood rods – 2 at core support, 2 at fire wall. All 4 can go to frame.
3. 4 rods in trunk. All can go to frame
4. Fix rusty floors
5. 2 extra body bolts allowed on each side
6. Can run radi barrel or radiator. Cannot be attached to frame
7. Sliders allowed
8. Can weld motor in no further forward than crank pulley and no further back than carburetor
9. Doors can be welded
10. No bar or mud tires on drive axle.
11. Build a cage to withstand a hit, no down bars to frame.
12. Lower engine cradle only.