



## TSB - SMF02

**Attention:** 

Please read before installation and advise vehicle owner.

When fitting a single mass flywheel replacement clutch package in certain vehicles, there may be an increase in transferred harmonic noises from the engine to the gearbox. This may present itself as a gearbox rattle. These transmitted noises in no way effect the performance of the clutch or the vehicle. Whilst every effort is made to reduce these noises by means of design, in some cases these noises are unavoidable



youtube.com/watch?v=NsvSb33xvxI



Scan with a QR app on your smart phone

Please note that these noises are not a warrantable issue



CLUTCH AND FLYWHEEL SPECIALISTS











